U.S. DEPARTMENT OF HOUSING AND URBAN DEVELOPMENT



OFFICE OF PUBLIC HOUSING

Special Applications Center 77 W. Jackson Blvd., Room 2401 Chicago, Illinois 60604-3507

Phone: (312) 353-6236 Fax: (312) 886-6413

JUL 0 9 2010

Mr. Robert Kulik Executive Director Woonsocket Housing Authority 679 Social Street Woonsocket, RI 02895-2026

Dear Mr. Kulik:

This is to acknowledge the Woonsocket Housing Authority's (WHA) application for the demolition of 5 dwelling buildings containing 36 dwelling units at Morin Heights (RI003000001) and 4 non-dwelling buildings and 28 dwelling buildings containing 144 dwelling units at Veterans Memorial (RI1003000002). The Special Applications Center (SAC) received this application on November 20, 2009, via the Public and Indian Housing Information Center (PIC), as applications DDA0003804 and DDA0003794. The Department's Offices of Public Housing and Fair Housing and Equal Opportunity are conducting simultaneous reviews of these applications.

On April 20-21, 2010, Arona Wiley, Naitik Patel and Alex Nasser of the Special Applications Center (SAC) made an on-site visit to verify the physical condition of the Morin Heights and Veterans Memorial projects. The SAC team inspected the exteriors of buildings as well as the interiors of some occupied and vacant units. Morin Heights is a 67 year old project and Veterans Memorial is a 57 year old project. The SAC team reviewed the physical needs assessment report dated April 24, 2009, revised on January 20, 2010. The last inspection performed by the Department's Real Estate Assessment Center (REAC) was on January 29, 2009. The final score for Morin Heights was 70 out of 100 and 73 out of 100 for Veterans Memorial. Based on the SAC team site visit and the REAC inspection, the SAC team determined that the buildings appear to be physically sound, but the units appeared to be undersized and in need of certain repairs and modernization.

The Department has generated Estimated Rehabilitation Cost spreadsheets. The work items in these spreadsheets are based on the Physical Needs Assessment reports and observation made during the site visit. The SAC has determined that some estimates for cost of rehabilitation are not permissible expenditures. Based on its analysis, the SAC estimated the rehabilitation cost for Morin Heights to be \$3,991,416, which is 44.70 percent of Total Development Cost (TDC) and the rehabilitation cost for Veterans Memorial to be \$8,062,547, which is 23.84 percent of TDC. The Department generally does not consider rehabilitation costs below 57.14 percent of TDC for non-elevator buildings as meeting the cost-test of the two-part demolition justification under 24 CFR § 970.15. Accordingly, at this time, it does not appear that the Public Housing Property is eligible for demolition. The WHA is invited to provide the SAC with information contrary to the enclosed spreadsheets or other supplemental information which it believes evidences that one or both of these projects meets the cost-test requirement for demolition. The

TDC tables for these projects are as follows:

TDC pe		7, Type of Structure: Providence Morin H	
Bedroom Size	Number of Unit	TDC/Unit	Total Cost
1-BR	4	\$172,777.00	\$691,108.00
2-BR	8	\$204,988.00	\$1,639,904.00
3-BR	9	\$244,365.00	\$2,199,285.00
4-BR	12	\$287,816.00	\$3,453,792.00
5-BR	3	\$315,177.00	\$945,531.00
	TO	TAL	\$8,929,620.00

TDC pe		7, Type of Structure: ovidence Veterans I	
Bedroom Size	Number of Unit	TDC/Unit	Total Cost
1-BR	4	\$172,777.00	\$691,108.00
2-BR	67	\$204,988.00	\$13,734,196.00
3-BR	65	\$244,365.00	\$15,883,723.00
4-BR	10	\$287,816.00	\$2,878,160.00
5-BR	2	\$315,177.00	\$630,354.00
	TO	TAL	\$33,817,543.00

Resident Consultation

24 CFR § 970.9(a) requires that an application for demolition be developed in consultation with the tenants of the proposed project. Please provide:

- How consultation with the residents of the Morin Heights residents was achieved.
- Documentation that translation service was provided for the Hispanic residents at Morin Heights, including (1) minutes and/or recordings (in Spanish and/or English) of meetings between HA representatives and tenants regarding the proposed demolition; and (2) details of the participation of interpreters.
- Notices, agendas and sign-in sheets of meetings that have taken place at Morin Heights.

Citizens Groups

The Department has received comments about these demolition applications from several citizen groups and other organizations, including NeighborWorks Blackstone River Valley, the Saint James Baptist Church, Family Resources Community Action, and Rhode Island Legal Services. The Department is reviewing and considering all of the comments provided by these entities in making its determination to approve or disapprove the WHA's demolition applications. WHA certified that it is in compliance with all applicable requirements for Section 18 of the U.S. Housing Act of 1937 Act and 24 CFR Part 970. Pursuant to 24 CFR § 970.29, the Department will disapprove an application for demolition if it determines that any certification

made by the WHA in its applications is clearly inconsistent with any information and data available to the Department.

Availability of Low In-Housing

Please provide the status of your public housing waiting list.

DDA0003003 Approval

On May 29, 2009, the Department approved the disposition of 26 dwelling buildings containing 51 Scattered Sites units; the WHA was authorized to dispose of the site at the Fair Market Value (FMV) of \$11,896,872. The WHA realized net proceeds from this disposition and proposed to use the proceeds from the sale to rehabilitate/upgrade units in its public housing inventory as identified below. The Department approved this use of proceeds in its May 29, 2009 approval.

Development Number	Development Name	Description of Work	Estimated Cost
RI003000007 Amp 001	Morin Heights	 Lead Removal Fire Code 	\$6,480,000 \$1,620,000
		3. Kitchen & Bathrooms	Subtotal: \$\frac{\$4,050,000}{12,150,000}\$
RI003000007 Amp 002	Veteran's Memorial	Lead Removal Fire Codes Kitchen & Bathrooms	\$12,000,000 \$3,000,000 \$7,500,000 Subtotal: \$22,500,000
Total			Unfunded: \$34,650.000

On July 14, 2009, the Department approved an amendment to (1) modify of the FMV of the Public Housing Property from \$11,896,872 to \$5,948.46 to reflect the correct FMV of the Public Housing Property at the time of the WHA submitted its disposition application in January 2008 (based on a Comparative Market Analysis (CMA)); and (2) to request an adjustment in the FMV of the Public Housing Property from \$5,948.46 to \$4,461,32 due to a downtown in the local real estate market. On June 3, 2010, as modified on June 30, 2010, the Department received a request for a further amendment to this disposition to reflect a modified FMV of \$2,295,000 due to the depressed market conditions. The Department is reviewing that request separately and a decision will be forthcoming.

With respect to the use of proceeds as identified above, please confirm that the WHA still plans to use the proceeds (in the final amount approved by the Department) for these purposes, and if so, provide a specific details on how the proceeds will be used, including the units and buildings where the proceeds will be used and a statement of work for the repair and modernization work.

CFFP (Capital Fund Financing Projects)

The HA received approval for the execution of Capital Fund Financing bonds on January 20, 2004, that entailed the issuance of bonds totaling \$9,665,000. Section 18 of the U.S. Housing Act of 1937 requires the housing authority to prepay modernization debt associated with the project, unless a waiver of this requirement is obtained. HUD is not issuing such a waiver pursuant to this letter. The PHA is therefore required to prepay any Capital Fund Financing Program (CFFP) proceeds used for the modernization of project numbers RI3000002, and RI3000001. Furthermore, pursuant to Section 30 HUD limits debt service associated with CFFP financings to 33% of the projected receipt of Capital Funds.

Please be aware that the demolition of the 184 units will affect your operating subsidy eligibility significantly.

Fair Housing and Equal Opportunity (FHEO)

- In making the decision to demolish 184 units of family public housing, did the HA take into account (a) the information provided in the 2009 Woonsocket PHA Plan which stated high levels of need for affordable housing and reported a public housing waiting list with 807 applicants, with approximately 69% waiting for family units; and (b) the 327 applicants on the current waiting list for family public housing? Please provide a detailed explanation.
- Was the HA's decision to demolish and dispose of family public housing influenced by the City's policy of reducing the overall level of housing affordability in Woonsocket from 16.5% to 12.5%? Please provide a detailed explanation. (Note: The policy of reducing housing affordability is stated as POLICY H-4.2 on page H-22 of the City's DRAFT Comprehensive Plan Five-year Update dated April 12, 2010, posted on the City's web site.)
- What are the HA's reasons for deciding to demolish or dispose of so much of its family housing but none of its elderly/disabled housing? Please provide a detailed explanation for this decision. (Note: Occupants of the HA's family public housing, including Morin Heights, Veteran's Memorial, and scattered sites, are approximately 62% minority and 38% non-Hispanic white; and occupants of the HA's elderly/disabled units are approximately 8% minority and 92% non-Hispanic white. Applicants on the HA's current family waiting list are approximately 51% Hispanic, 12% African American, and 1% Asian; while applicants on the elderly/disabled waiting list are 11% Hispanic, 8% African American, and 1% Asian.)
- Why did the HA reverse its June 2008 position stating that limited resources should be directed to maintaining the multifamily units at Morin Heights and Veteran's Memorial, and instead propose in October 2009 to demolish 184 of these same multifamily units? Please provide a detailed explanation. [See the June 2, 2008 memo from HA Deputy Director Duncan C. Speel to the HUD Special Applications Center, providing justification for sale of 51 scattered site units and stating that the HA's "limited dollars are better invested into the contiguous properties, Morin Heights (282 units) and Veteran's Memorial (296 units) multifamily apartments. . . . [i]t is more cost effective . . . and more direct to our mission . . . to

meet codes and keep the doors open with every dollar we can get for our contiguous multi family units."]

- What alternatives the HA has considered to avoid such substantial demolition of family housing?
- Does the HA have any minutes and/or recordings of Resident Advisory Board meetings, detailing any motions and/or votes that took place in regard to the proposed demolition? If yes, please submit these minutes and/or recordings.

If you have any questions regarding the FHEO requests, please contact Program Compliance Branch Chief Merryl Gibbs by email at *Merryl.Gibbs@hud.gov* or by telephone at 617-994-8305.

If you have questions concerning your applications or this request, please feel free to contact Ms. Arona Wiley, Public Housing Revitalization Specialist of the SAC, at 312-913-8021. As always my staff and I are available to assist you in anyway possible. As you continue to work with the Department in its review of these applications, I urge you to maintain an open dialogue with the Boston HUB Office, the Department's Boston Office of FHEO, your residents, citizen groups, and local officials.

Sincerely,

Ainars Rodins, P.E.

Director

cc: Steven Fischbach, Esq.
Rhode Island Legal Services

Joe Garlick, Executive Director Ms. Glenda Byhouwer, President NeighborWorks Blackstone River Valley

Reverend Dr. Sammy C. Vaughn, Pastor Saint James Baptist Church

Ms. Nancy L. Benoit, Chair, Board of Directors Family Resources Community Action

		ğ													
	Site infrastructure	Item													
		unit													
		unit cost	2009 TDC total	2009 TDC/unit		Standard Units (Accessible units	Oty of units (nenovated)	Average SF/unit	Aggregate Unit S	Unit SF (excisting	Only of bathroom	Unit mix (existing	Oty of units (exis	
		qty				renovated)	(renovated	ovated)	(existing)	¥F (excisting)	_	Oty of bathrooms per unit (existing)	=	ding)	
		coat	_						_			_			ì
		18R	691,108	172,777		ω	_	4	_	2,464	616	1.0	11%	4	188
		2BR	1,639,904	204,988		7	=	8		7,880	985	1.0	22%	8	2BR
		9BR	2,199,285	244,365		80	1	9		10,215	1,135	2.0	25%	9	3BR
		48R (3,453,792	287,816	_	11	-1	12		16,236	1,353	2.0	33%	12	4BR 5
		5BR #4	945,531 8	315,177		2	-	ဖ		4,059	1,353	3.0	8%	3	58R
		subtotal g	8,929,620		88	31	ເກ	8	1.135	40,854			100%	88	Total
		grand total													
Added electric service. New the potential to ability of drug		comments													
Added electrical loads (HVAC, Washer/Dryer service, New service to be run underground, the potential for damage during storm events ability of drug dealers to "mark" locations by															
Washer/Drye underground storm events locations by															

means means	means means means means	means means	meens meens	eource
Resurface Drives and Parking Areas Resurface Streets and Drives Resurface Parking Spaces	Repair Sidewalks / Add New Sidewalks demolition repair sidewalk reversidewalk grading/sed	Regrading at Buildings/welloc/drives Secondary Sec	New Electrical Feeds to Each Building demolition accomplion 2 - 2 PVG Service Conduits New Electrical Panels	Rem Site infrastructure
क्षं क्षं	E & & S	BCY MSF		unit
1.25 1.25	7.15 3.96 3.96 20.00	3.56 4.00 350.00	1.59 1.65 7.60 400.00	unit cost
4,000.00	12.00 50.00 58.00	7.11 21.30 0.50	3,600 00 3,600 00 3,600 00 1,4	qty
5,000.00 5,000.00	85.80 198.00 229.68 20.00	25.31 85.20 175.00	5,724.00 6,680.00 27,360.00 440,000.00	CORT
	343 792 919 80	101 341 700		1BR
	1,59.4 1,837 1,60	202 682 1,400		2BR
	772 1,782 2,067 180	228 767 1,575		9BR
	1,030 2,376 2,756 2,756	304 1,022 2,100		48R
	257 594 689 60	76 256 525		SBR
5,000 5,000 10,000	3,089 7,128 8,268 720 19,205	911 3,067 6,300 10,278	5,724 6,660 27,360 1,440,000	aubtotal
10,000	19,205	10,278	1,479,744	grand total
Roadways, drives and existing parking lots require resurfacing. 4,000 SF of roadway and driveway existing. 4000 SF or parking spaces existing.	This is paving work associated with grading work described above, along with general sidewalk repair. Average 108 sturit Average 50 sturit 58 if new sidewalk	work is associated with the establishment of low parking areas, in order to transition from the parking lot to the unit entrances and the excessible routed is a manner that mode is the IFAS accessibility requirements. Each unit. 32 v. 6 v if deep area of work (32 lotal unit frontage). 32 x 6 area per unit. 32 x 6 area per unit.	Added electrical loads (HVAC, Washer/Dryer) requires edditional service. New service to be nur underground, for 2 reasons: it nihimizes the potential for damage during storm events, and also eliminates the ability of drug dealers to "mark" locations by hanging shoes from overhead lines. 100 Li per bidg. 100 Li per bidg. 100 Li per bidg.	comments

means	means	means	means	means	means	means	means		Surem	means	
								Repair			Site Imp
fence	mulch	Activity Panel	Guardrail Pipe 36	Ladder, Vertical	Slide, Straight, Poly	Post, Alum 2-3/8 square	Deck, squere, poly, 48° x 48°	Repair Existing Play Areas	shrubs/groundcover	Trees	Site Improvemente Repair Erosian Issues
14	MSF	8	5	8	88	5	88		88	8	
26	450	990	150	880	2,100	78	2,025		×	28	
36		3	12	3	3	6	ω		1	-	
1,005	374	2,970	1,800	2,640	6,300	468	6,075		16	10	
									42	đ	
									128	80	
						_			144	90	
	-								192	120	
									48	30	
1,005	374	2,970	1,800	2,640	6,300	468	6,075		576	360	
								Repair equipment and ground surfaces at 3 existing play areas. Scope includes replacement of one section of deck, 2 posts, onew sities, one ladder, one 4 section of guardrali, and one activity panel per play area. Provide new mulch.			Scope includes a 12' wide erea of landscaping on each loce of the unit Landscaping intended to provide erosion control and shade planting adjacent to units and pallos to reduce solar gain inside units and reduce Heat Island.

means means means	means	means	means	means means	Bid Based means means means	means
New Thormal Glazed Alum Windows EA New windows - 18R EA New windows - 28R EA New windows - 38R EA New windows - 48R EA	Rapilace Interior Doors - IB. Rapilace Interior Doors - IB. Rapilace Interior Doors - 2Br Rapilace Interior Doors - 3Br Rapilace Interior Doors - 5Br Rapilace Interior Doors - 5Br Rapilace Interior Doors - 5Br Rapilace Door Harrhware - 1BR Rapilace Door Harrhware - 1BR Rapilace Door Harrhware - 4BR Rapilace Door Harrhware - 4BR Rapilace Interior Doors - Partiny/Laundry Rapilace Interior Doors - Partiny/Laundry Damo Interior Doors - 1Br Damo Interior Doors - 2Br EA Damo Interior Doors - 5Br EA EA EA EA EA EA EA EA EA E	Raphase Examics Doors dearno adust entry doors, screen doors, framed EA new perhung steel entry doors EA New screen doors EA New screen doors EA New screen doors EA New screen doors EA New perhung steel entry doors EA New perhung steel entry doors EA Dearit work © breazeway doors EA New perhung steel entry doors EA Dearit work © breazeway doors EA	New Wood Floor Wood Iloor Oak - 1Br Wood Iloor Oak - 2Br Wood Iloor Oak - 3Br Geno asking wood Flooring - 1BR Geno asking wood Flooring - 2BR Geno asking wood Flooring - 4BR Geno asking wood Flooring - 5BR	Repair Exterior Soffits/Eaves Plaster repair at soffits Part work at serves If	Inspection/Repair of Structures, hand rails Structural Engineer Inspection/Design HR Repair/Replace/Demaged Hand Rails UF Repair/Replace/Repoint demaged brick SF Repair/Replace/Repoint demaged brick SF	New Site Furnishings (benches, bike racks, mail center) Trash Recoplacies as a least structural Deficiencies
450.00 450.00 450.00	179.00 179.00 179.00 179.00 142.00 142.00 142.00 142.00 142.00 142.00 142.00 143.00 19.00 10.00 10.00 10.00 10.00 10.00	79.50 335.00 495.00 695.00 278.60 795.00 335.00 275.00	5.59 5.59 5.59 5.59 5.59 0.72 0.72 0.72 0.72	29.50	36.00 80.00 31.00 10.00 12.50 5.00 12.50 20.00	unit unit cost dy
1.75 787.50 2.25 1,012.50 2.75 1,237.50 3.50 1,575.00	2.50 2.50	2 159.00 2 2 710.00 1 2 810.00 1 2 139.00 2 2 139.00 2 2 159.60 2 0.25 88.75 0 0.25 88.75	\$7.57	3.0 88.50 92 128.80	2,880 00 310 00 82 50 250 00	790 W
8,100 11,138	2,506 6,444 8,861 1,988 5,112 7,029 358 180 180 180 251 644 985	686 1,272 1,431 2,840 5,840 6,350 1,620 6,460 7,250 5,64 1,112 1,251 2,230 4,461 5,018 385 3,018 3,018 385 3,018 3,018	284.89 3,164.46 4,480.74 4,480.74 3300.56 4,255.20 5,516.10	177 708 797 269 1,090 1,159	2,480 2,790	25A 3BR
18,900	15,038 4,298 11,928 3,408 240 60	1,998 477 8,520 2,130 9,720 2,430 1,668 417 6,681 1,673	7,390,15 1,847,54 8,767,44 2,191,86	1,062 266 1,546 388	3720 930 750 188	48R 56R Fu
3,150 8,100 11,138 18,900	2,506 6,444 4,296 1,988	5/724 5/560 25,660 5,004 5,004 20,074 80 356 80 81 84,681 84,681	1.284.89 3.164.49 7.390.15 1.390.15 1.390.5 5.265.00 5.265.00 6.265.00 6.2767.44 2.191.86 40.229	3,009 4,379 7,388 7,388	2,880 11,160 2,280 9,000 25,290 25,290	
Aluminum windows with 34* insulating glass. 1.75 windowe/unit 2.25 windowe/unit 2.75 windowe/unit 3.5 windows/unit	Masonilo pre-hung doors 3.5 doors/unit 4.5 doors/unit 6.5 doors/unit 7.5 doors/unit 8.6 doors/unit 8.6 doors/unit 8.6 doors/unit 9.7 doors/unit 9.7 doors/unit 9.7 doors/unit 9.8 doors/unit	note that only 1 door included for 1 Br units occurs at flat buildings only, 1 breazewey per 4 units occurs at flat buildings only, 1 breazewey per 4 units occurs at flat buildings only, 1 breazewey per 4 units occurs at flat buildings only, 1 breazewey per 4 units	New carpet and pad in all areas except kitchen, baths, mech rooms, laundry.	New eave deeligh to accompany Finish upgrades. Repair damaged soffliss and replace plaster as required by installation of new plumbing and sec work described below. paint all eaves and sofflis.	80 hrs 3 \$125/hour. Major structural failures were not observed, but a detailed trapection by an engineer is required. There are instances of concrete spalling, damaged brick morter joints, and corrosion at steel beloony railings.	Comments Basic scope assumption is that each building (8 units) would receive 4 benches, 2 trash receptacles, one dog walk station and one bike rack.

means	means means means means means means means means means	means	means	means means	means	COLLOS
Renovate Exist 26° Van 1120 Vin Tho	Renovate Kildnen Dost-ic sink redige range range Vori II Demo	Pant Interior Page Page Page Page Page Page Page Page	New Dose/foor	New Stair Tree	Dage Dage	tem
Se Existing Bath's Se' vanity cab Doss' formed oounler wanity sink won'ty sink Worfoliel Ubdishower Illudishower Threshold Threshold	Perrovate Kilchen Dass carbs/well caths Dost-formed counter sink refrigerator range range hood VCT floor Deno existing base cathinds Deno existing hast cabinats	Pant Infaror Paint Walls - 18R Paint Walls - 28R Paint Tim - 18R Paint Tim - 38R Paint Tim - 48R Paint Tim - 48R Paint Tim - 58R Paint Callings - 18R Paint Callings - 18R Paint Callings - 18R Paint Callings - 18R Paint Callings - 38R Paint Callings - 58R Paint Callings - 58R	edeconfinition in the interest of the interest	New Stair Trends and Rallings New Wood treads	New windows - 58A New mini-blinds - 18A New mini-blinds - 28A New mini-blinds - 38A New mini-blinds - 38A New mini-blinds - 48A New	
8 7 8 8 8 8 3 = 3	55899995	祝祝祝祝祝 <u></u>	Who who was a way of the way of t	\(\frac{1}{2}\)		E I
400 00 28 00 425 00 425 00 1,150 00 1,150 00 1,150 00 1,150 00 1,150 00 1,150 00	435.00 560.00 760.00 450.00 242.00 242.00 9	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	4 33 4 33 4 33 4 33 4 33 84 76 84 76 84 76 84 76 94 78 94 78 94 78 94 78 94 78	90.50	450 80 71.77 71.77 71.77 71.71 71.71 23 23 23 23 23 23	unit coet
<u>-8</u>	280 16 8 8	1,791,09 2,864,00 3,3300,14 3,330,14 404,00 3,884,00 3,884,00 642,00 767,00 985,00 1,016,00 616,00 1,1185,00 1,185,00 1,383,00 1,383,00	223.89 358.00 412.50 491.75 491.75 491.75 7.00 5.50 1.76 1.76 2.25 2.25 2.25 2.25 3.50 4.00	12.00 39.00	1,75 1,75 2,25 2,75 4,00 4,00 4,00 2,00 3,00 4,00 4,00 4,00 4,00 4,00 4,00 4	σtν
400.00 78.00 425.00 325.00 385.00 1,150.00 305.00 305.00 77 77	870.00 416.00 560.00 750.00 4450.00 242.00 188.80 72	1,432,87 2,291,20 2,640,11 3,147,20 3,147,20 3,147,20 513,60 613,60 743,20 492,80 7492,80 1982,40 1,082,40	969.43 1,580.14 1,786.20 2,129.26 2,129.26 2,129.26 38.1.4 466.18 583.08 100.10 128.7 20.2 20.2 20.2 20.2 20.2 20.2 20.2 20	1,086,00 546,00	1,800,00 161,549 161,56 197,20 250,59 286,64 39 39 79	80
1,600 312 1,700 1,300 1,540 4,600 1,220 1,220 336	3,490 00 1,664 3,240 1,800 1,800 968 755 286 286	5,731 1,233 1,971	3,978 1,187	4,344.00 2,184.00	158	188
3,200 824 824 3,400 2,800 3,080 9,200 2,440 576 672	6,960.00 3,328 4,480 6,000 3,600 1,336 1,510 573 573	18,330 4,109	12,401 3,051	8,688 4,368	1,291	288
3,600 702 3,825 2,925 3,465 10,350 10,350 2,745 648 756	7,830,00 3,744 5,040 6,750 4,050 2,178 1,699 644	23,761 5,522 5,172	15,076 4,196	9,774 4,914	1,775	ann ann
9,600 1,872 10,200 9,240 13,800 3,660 1,296 2,016	10,440,00 4,992 6,720 9,000 2,000 2,204 2,286 859 859	37,766 8,918	25,551 7,120 2,402	13,032 6,552	3,012	480
2,400 488 2,550 1,950 2,310 3,450 915 924 504	2,610.00 1,248 1,680 2,250 1,350 7,26 566 586 215	9,442	6,388 2,034	3,258 1,638	5,400 861 870	200
20,400 3,978 10,575 19,635 41,400 41,400 3,132 4,284	31,320 00 14,976 20,160 27,000 18,200 8,712 6,797 2,578 2,578 130,320	5.731 18.330 23.761 37.762 37.762 1.9442 1.9442 1.994 5.522 6.916	3,878 12,401 16,076 25,551 6,386 1,187 3,051 4,196 7,120 1,000 1,000 1,416 686 87,816	39,096 19,656 58,752	\$4,400 \$5,400 \$1,775 \$1,775 \$3,072 \$61 \$61 \$45 \$45 \$45 \$45 \$46 \$270	1
	19 0,920	149,994	87,816	58,752	97870 (208) 56, 482	
Same bathroom design used for all units. Note that 4BR and 5BR units have i 5 betts. For these, he work associated with the tub is only counied once but other items counted twice.	Same kitchen design used for ell units.	Paint all interior spaces.	New baseboard and fifm package proposed 3-1/2" stock pine base 16.3 LF/Door 0 55.20/fi = \$84.76	Existing stairs are very narrow (+/-3) and steep (6" risers). Upgrade of finishes will improve perceptions of this item.	Oomments 1.75 windows/unit 1.75 windows/unit 2.75 windows/unit 2.75 windows/unit 2.75 windows/unit 2.75 windows/unit 3.5 windows/unit 4.0 windows/unit 2.75 windows/unit 2.75 windows/unit 2.75 windows/unit 2.75 windows/unit 2.75 windows/unit 3.5 windows/unit 4.0 windows/unit	

meens	means means means means means means	means	means	meens meens meens meens meens	meens meens meens meens	means means means means means means means	eouroe
Electrical Provide New house meter Provide new house panel New circuits, switches and outlets - 18R st New circuits, switches and outlets - 28R st New circuits, switches and outlets - 38R st Hardwired smoke deadons - 18R EA Hardwired smoke deadons - 38R EA Hardwired smoke deadons - 38R EA Hardwired smoke deadons - 38R EA Demo existing electrical writing flixtures CLF	Plumbing Rapain/Rapiace deteriorated plumbing lines Rapiace gas piping from meter to pi of use Rapiace gas piping from meter to pi of use LF Rapiace gas piping to copper Convet galv piping to copper New San Piping at new itstures New San Piping at new itstures LF Submeter and shut off valve at each unit EA	Mechanitosi New HNAC system - 1BR sf New HNAC system - 2BR sf New HNAC system - 3BR sf Abd should show a facility of condenses sf Abd should fans a leasing baths - 1BR EA Add should fans a leasing baths - 3BR EA Add should fans a leasing baths - 3BR EA Add should fans a leasing baths - 3BR EA Add should fans a leasing baths - 3BR EA Add should fans a leasing baths - 5BR EA New year maters Interest New year maters Interest Interest Interest	Visitability Modifications Widen entrance to noceive accessible door. EA	Acquair plaster out study size or receive insul. Unit 3/4 rigid insul in added realis - 18R3 SF 3/4 rigid insul in added realis - 18R3 SF 3/4 rigid insul in added realis - 28R3 SF 3/4 rigid insul in added realis - 28R3 SF 3/4 rigid insul in added realis - 58R3 SF 3/4 rigid insul in added realis - 58R3 SF 3/4 rigid insul in added realis - 58R3 SF 3/4 rigid insul in added realis - 58R3 SF 3/4 rigid insul in added realis - 58R3 SF 3/4 rigid insul in added realis - 58R3 SF	Added Thermal Insulation in attics and walls R-30 blown insulation at attics - IBR SF R-30 blown resulation at attics - IBR SF R-30 blown insulation at attics - IBR SF R-30 blown insulation at attics - IBR SF R-30 blown insulation at attics - IBR SF	ceramic well tile (tub surround and wainscot) si lile becker beard shower curtain nod sea medicine cabinet Seap dath and lowel bet at tub Demo existing beth tub Demo existing half tub Demo existing well hung lavatory ea	ttem
1,800.00 1,8	5,00 19,65 1,250,00 110,00 19,50 250,00	3 67 3 67 3 67 3 67 3 67 3 67 125 00 125 00 125 00 125 00 125 00 125 00 125 00 125 00 125 00 125 00	625.00	0.88 0.80 0.80 0.80 0.80 0.80 0.80	1.12 1.12 1.12 1.12	6.95 3.63 71.50 117.00 20.50 108	unit coet
36 9,900 56 1,849 516 1,849 516 2,965 1,1363 3,405 1,363 4,059 1,363 4,059 1,363 150 5 250 6 300 7 350 7 4,059 1,510	50 250 20 383 10 1,250 10 1,000 50 975 1 250	1 30000 1 125.00 1 125.00 1 125.00 2 250.00 2 250.00	1 625.00	1 1780 OI 6822 1,2607 ZO 1,267 ZO 1,1618 1,1457 ZO 1,1608 1,726 OG 1,608 1,726 OG	308 344 96 443 551 80 568 635 90 677 757 98 677 757 98		qty cost
7,392 23,640 900 2,000 6,440 12,890	1,000 2,000 1,572 3,144 1,572 10,000 4,000 8,000 1,000 7,800 1,000 2,000	1,200 2,400 500 1,000	1,875 4,375	3,183 10,138	4	770 7,339 317 3,833 318 572 88 596 82 164 82 164 82 864 82 566 82 566 82 566 82 566 82 566 83 566 84 566 85 566 85 566 86 572 86 566 87 566 88 566	1BA 2BA 3
2,700 4,200 1,200 1,4490 19,320 4,830	2,250 3,000 750 3,537 4,716 1,179 11,250 15,000 3,750 9,000 12,000 3,000 8,776 11,700 2,925 2,250 3,000 750	2,700 9,600 900 1,125 1,500 975 1,125 3,000 750	5,000 6,975 1,250	13,116 20,833 5,208	9,092	257 16.513 312 8,225 644 858 653 2,808 165 492 172 2,592 972 2,592 972 2,592 972 1,529 973 1,529 1,520	3BR 4BR 5BR
9,900 64,900 7,395 30,645 48,708 18,708 12,707 2,000 2,700 1,200 1,200 2,786 9,786	9,000 14,148 45,000 35,100 9,000 148,246	10,800 4,500 1,000 1,000 1,000 1,000 750 750	19,375 19,375	3,193 3,193 10,138 13,116 20,833 5,208 78,966	1,380 4,413 5,720 9,092 2,273	39,907 20,843 2,574 5,967 1,046 5,596 2,754 3,443 224,100	subtotal
285,922	148,248	21,675	19,375	78,966			grand total
Addition of HVAC equipment, Washers, Dryers and Dishwashers requires new service and distribution at each unit. Indicated in Ist, Irving, BR's, Hall.	All damaged piping to be replaced, and new piping to be provided as required for new kitcher and bath configurations. several leaks observed in units, particularly at kitchers below 2nd floor bathrooms.	Existing units include floor heaters, gas-fired with not ductwork distribution. A new forced air system with aderior condensers is TBD 1780 1780 1780 1780 1780 1780 1780 1780	Accessible entrance provided at each unit. This applies to 516 units.	Repairs to support additional and replace deteriorated supports.	Buildings lack insulation in entire envelope. Blown insulation is proposed for aftic spaces. Pigid insulation is proposed to be added to the limited of exterior wells (behind GWE).		comments

Renovatie Edisting Common Bulldings UFAS modifications - Common Bulldings LS 60,000 1 60,000 60,000 60,000 Allowance for UFAS renovati	AHA Administration 3% AHA Administration 3% New Total 3,991,416 2009 IDC 9,229,620 % of TDC 44,70%	General Conditions LS 249,189.25 1 248,189.25 249,189.25	SUBTOTAL 3,102,366	Asbedios Abatement Asbedios Abatement Overall Project Asbedios Abatement EA 2,500.00 90,000.00	ourse from unit unit cost gry cost 18R 28R 48R 58R subicial grand total comments
Allowence for UFAS renovations at Learning Center	, 0 . 0 . 1			Ashestos abatement for all residential and non-residential buildings. Cost based on 2008 actual demolition cost for 149 units.	commente

Conversion factions based on 28'r unit SF 29H SF 1BR 28H 38H 48H 48H 58R

985 616 985 1135 1353

63% 100% 115% 137% 137%

Unit mix (existing) Dity of bethnooms per unit (existing) Unit SF (existing) Unit SF (existing) Aggregate Unit SF (existing)
r unit (existing) existing)

8 929 820	25 531	3 453 790	2 199 285	1 639 974	801 108
	315,177	287,816	244,365	204,968	172,777
36					
31	2	===	8	7	3
5	_	-1	-	1	1
88	3	12	9	8	4
1,135					
40,854	4,059	16,236	10,215	7,880	2,464
	1,353	1,353	1,135	985	919
	3.0	2.0	2.0	1.0	1.0
100%	8%	33%	25%	22%	11%
36	3	12	9	8	4
iotal	201	#EX	388	281	184

means means means means means means means means	means means	means	means means means	means means	means means	Pource	
Repair Existing Play Areas Deck, exports, poly, 46" x 46" Post, Alum 2-38 square Sinds, Shraight, boly Laddar, Vertical Guardrail Pigs 36" Achielly Panel Ierco	Site Improvements Flepair Erosion Issues Trees Shrubs/groundcover	Resulface Drives and Parking Areas Resulface Streets and Drives Resulface Parking Spaces	Ropali Sidewalks / Add New Sidewalks demolition repair sidewalk repair sidewalk repair sidewalk rew s	Regrecting at Buildings/wallss/drives accavation grading sod	New Electrical Feacts to Each Building demolition accuration 2 2º PVG Services Conduits New Electrical Panels	Item Site infrastructure	
H N N N N N N N N N N N N N N N N N N N	8 8	क्ष	E St St St	BCY SY MSF	<u> </u>	5	
2,025 78 2,1100 880 1890 980 980 980	8 8	1.25 4.0 1.25 4.0	7,15 3,96 3,96 20,00	3.56 4.00 350.00	1.59 1.58 3.6 7.60 3.6 400.00 3.6	unit court qty	Unit SF (existing) Augment of Int SF (existing) Average SF/unit (existing) Average SF/unit (existing) Oby of units (renovated) Accessible units (renovated) Sandard Units (renovated) Sandard Units (renovated) Sandard Units (renovated)
3 6,075 6 488 3 6,300 3 2,840 12 1,900 1 2,970 1 374 30 1,005		4,000.00 5,000.00 4,000.00 5,000.00	12.00 85.80 50.00 196.00 58.00 229.68 1.00 20.00	7.11 25.31 21.30 85.20 0.50 175.00	3,600 00 5,724 00 3,600 00 6,860 00 3,600 00 7,360 00 3,600 00 1,440,000 00	OO BIT) was
56 2 6 8 8 8 9	16 40		0 343 0 792 6 919 0 80	700			616 2,484 4 4 4 1 172,777 691,108 1
	80		686 772 1,584 1,782 1,837 2,067 160 180	202 228 682 767 1,400 1,575		2BR 3BR	7,880 11,235 7,880 10,215 8 9 1 1 7 8 204,988 244,365 589,904 2,199,285
	120		2 1,030 2 2,376 7 2,756 0 240	8 304 7 1,022 5 2,100		4BR 58R	1,353 16,236 12 12 1 1 11 11 287,816 3,453,792 9
6,075 488 6,300 1,800 2,940 2,970 2,970 1,075 21,632	30 360 48 576	5,000 5,000 10,000	257 594 7,128 689 8,268 7,20 19,205	76 911 256 3,067 525 6,300 10,278	5724 6,660 77,360 1,440,000 1,479,744	aubtotal	1,383 40,864 4,069 1,135 1,135 3 3 3 5 1 1 2 36 3 3 5 2 36 36 5 1,235 1,355 1,
21,632		10,000	19,205	10,278	1,479,744	grænd totel	
biodor, one of section of guardrall, and one activity panel per play area. Provide new mulch.	Scope includes a 12 wide area of landscaping on each face of the unit Landscaping intended to provide erosion control and shade planting adjacent to units and patios to reduce soler gain inside units and reduce that island. Repair equipment and ground surfaces at 3 adding play area. Scope in regain equipment and ground surfaces at 3 adding play area.	Roadhays, drives and existing parking lots require resurfacing 4,000 SF or readway and driveway existing 4000 SF or parking spaces existing	This is paving work associated with grading work described above, along with pareral elebenatik repair. Average 108 et whit Average 50 strait 56 if new eldewalk.	order to rearsition from the parking of to the unit enteroree and the accessible noutee in a manner that meds the UFAS accessibility requirements. Each unit: 22 x 6" 1" deep area of work (32" total unit frontage) 22 x 6" area per unit 32" x 6" area per unit	Added electrical loads (HVAC, Washer/Dyer) requires additional service. New service to be run underground, for 2 nessons: it minimizes the potential for damage during atom events, and also eliminates the ability of thay dealers to "mark" locations by hanging shoes from overhead lines. 100 LI per blog. 100 LI per blog. See below for information regarding new parking areas. This grading work is associated with the establishment of new parking areas, in	comments	

means means means means	means	means	means	meens	Bid Based means means means	eource moens
New Thormal Glazzed Alum Windows Rew windows - IBR New windows - 2BR New windows - 3BR New windows - 4BR	Replace Interior Doors - 18/ Replace Interior Doors - 28/ Replace Interior Doors - 28/ Replace Interior Doors - 38/ Replace Interior Doors - 38/ Replace Interior Doors - 58/ Replace Door Hardware - 18/ Replace Door Hardware - 18/ Replace Door Hardware - 38/ Replace Door Hardware - 38/ Replace Door Hardware - 58/ Replace Door Hardware -	Replace Exterior Doors. Geno estil entiry doors, ecreen doors, framel new pre-hung steel entiry doors pent work pent work hardware demo estil entiry doors, frames new pre-hung steel entiry doors pent work of breezeway doors hardware of breezeway doors	New Wood floor Cask - 18: Wood floor Cask - 28: Wood floor Cask - 38: Wood floor Cask - 48: Wood flooring - 188 demo additing wood Flooring - 188 demo additing wood Flooring - 488 demo additing wood Flooring - 488 demo additing wood Flooring - 588	Repair Exterior Soffine Exvoe: Pleaser repair at soffite Paint work at eaves	Inspection/Repair of Structures, hand rails Structural Engineer Inspection/Design Repair/Replace Demanged Hand Rails Repair/Replace/Repairit demanged brick Repair/Replace/Repairit demanged brick Repair/Replace/Repairit demanged brick	New Site Furnishings (banches, blike racks, mail center) Trash Receptacles Structural Deficiencies
EA A A			생 전 전 전 전 전 전 전 전 전 전 전 전 전 전 전 전 전 전 전	W SY	\$\frac{1}{2}\$	unit unit cost
450.00 1.75 787.50 450.00 2.25 1,012.50 450.00 2.75 1,237.50 450.00 3.50 1,575.00	179.00 3.50 628.50 179.00 4.50 805.50 179.00 7.00 1,283.00 179.00 7.00 1,283.00 179.00 3.50 44.70 142.00 3.50 781.00 142.00 5.50 781.00 142.00 8.00 1,183.00 142.00 8.00 1,83.00 142.00 8.00 1,83.50 142.00 8.00 1,83.50 160 4 6.00 179.00 0.50 0.50 180 0.50 0.50 1	79.50 2 159.00 385.00 2 710.00 485.00 2 180.00 69.50 2 139.00 7278.80 2 139.00 7278.90 0.25 19.80 385.00 0.25 88.75 69.50 0.25 17.38 275.00 0.25 88.75	5.58 57.57 32.1 22 5.58 70.89 385.56 5.58 89.22 487.86 5.58 110.97 615.83 5.58 110.97 615.85 5.59 10.72 30.54 0.72 462.00 30.54 0.72 851.28 512.90 0.72 1.014.78 730.62 0.72 1.014.78 730.62	29.50 3.0 88.50 1.40 92 178.80	96.00 80.00 2,880.00 91.00 10.00 310.00 12.50 5.00 62.50 12.50 20.00 250.00	et qfy coet
501 503 503 503 503 503 503 503 503 503 503	2,506 6,444 8,861 15,036	00 656 1,272 1,431 1,908 00 2,840 6,880 6,350 8,520 00 1,620 6,480 7,230 9,720 00 5,565 1,112 1,251 1,688 60 2,230 4,451 5,018 6,691 88 2,60 4,451 5,018 6,691 75 355 356 6,691 75 357 357 357	1,284.89 3,164.48 4,480.74 7,390.15 1 1,390.56 4,255.20 5,516.10 8,767.44 2	50 177 708 787 1,082 80 258 1,030 1,159 1,546 1	00 1,240 2,480 2,780 3,720 50 250 500 500 2,550 750 1,000 2,000 2,250 3,000	1BR 2BR 3BR 4BR
3,150 8,100 11,138 18,900	2,506 6,444 15,066 1,296 1,296 1,296 1,192 7,029 1,192 3,408	477 5,724 2,160 23,560 417 5,044 1,673 20,074 1,673 356 356 357 84,681	1,284,89 2,184,49 4,400,74 7,390,15 1,847,54 1,390,56 4,265,20 5,516,10 8,767,44 2,191,86 2,191,86 40,229	286 3,009 4,379 7,388 7,388	2,890 11,190 188 2,250 750 25,250 25,250	
Aluminum windows with 34f insulating glass. 1.75 windows/unit 2.25 windows/unit 2.25 windows/unit 3.55 windows/unit 3.55 windows/unit	Masonile pre-hung doors. 3.5 Goors/unit 4.5 Goors/unit 5.5 Goors/unit 7.5 Goors/unit 6.0 Goors/unit 6.5 Goors/unit	note that only 1 door included for 1 Br units cocurs at flat buildings only, 1 breazeway per 4 units cocurs at flat buildings only, 1 breazeway per 4 units cocurs at flat buildings only, 1 breazeway per 4 units cocurs at flat buildings only, 1 breazeway per 4 units	New carpet and pad in all areas except kitchen, baths, mech rooms, laundry.	New eave design to accompany Finish upgrades Repair demanged soffits and replace plaster as required by installation of new plumbing and size work described below. Danit all eaves and soffits.	60 hrs © \$125hour. Major structural failures were not observed, but a detailed inspection by an engineer is required. There are instances of concrete spalling, demaged brick morter joints, and corrosion at steel belicony railings.	comments Basic scope assumption is that each building (8 units) would receive 4 benches, 2 trash receptacles, one dog wellk station and one bike rack.

means	means means means means means means means means	means	means	means means	meens
Rerovato Existing Baths 35" varnity catb Dost-formed counter varnity sink varnity fittings WC/Totale ILb/shower Italy fittings Viriy fille floor Threshold	Harovats (IIchan base cabs/well cabs Dase cabs/well cabs Dase cabs/well cabs Dase cabs/well cabs dase dase dase dase dase dase dase das	Paint Indigor Paint Walls - 1899 Paint Walls - 2899 Paint Walls - 2899 Paint Walls - 3899 Paint Tim - 1899 Paint Tim - 1899 Paint Tim - 1899 Paint Tim - 3899 Paint Callings - 1899	New base/dow/inframers basedoard 198 New literature hadow tirm 198 New	New Stair Treeds and Railings New wood treeds New wood reads New Wo	New windows - 58R New min-blinds - 18R New min-blinds - 28R New min-blinds - 28R New min-blinds - 38R New min-blinds - 48R New min-blinds - 48R New min-blinds - 48R Demo windows - 18R Demo windows - 28R Demo windows - 28R Demo windows - 38R Demo windows - 48R
8 2 8 8 8 8 8	5548888	***************************************	Win	TIP	
400 00 425 00 325 00 1,150 00 305.00 305.00 1,2 00 305.00 1,4 00 305.00	435.00 26.00 750.00 450.00 450.00 242.00 242.00 9 9	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	4.33 4.33 4.33 4.33 84.76 84.76 84.76 84.76 84.76 84.76 84.76 84.76 84.76 84.76	90.50 14.00	## Operation of ## 1717 71.71 71.7
- 8	8 8 8 6 8	1,791 09 2,864 00 3,300 14 3,904 00 3,904 00 3,9	223.89 388.00 412.52 491.75 491.75 491.75 2.76 2.76 2.76 3.00 4.00	12.00 39.00	400 1,75 2,75 2,75 3,50 4,00 2 2 2 3 4
400.00 78.00 425.00 325.00 385.00 1,150.00 1,150.00 72 84.00	870.00 416.00 560.00 750.00 450.00 450.00 188.80 72 72	1,432.87 2,291.20 2,640.11 3,147.20 3,147.20 3,147.20 3,147.20 5,13.60 6,13.60 7,43.60 6,12.60 4,872.60 7,88.00 1,082.40 1,082.40	969.43 1,550.14 1,766.20 2,129.28 2,129.28 2,129.28 381.42 486.18 593.20 100.10 110.10 120.28 1578.08	1,086.00 546.00	1,800.00 125.44 161.35 197.20 250.99 286.84 39 39 90
1,800 312 1,700 1,300 1,540 1,520 1,220 1,220 338	3,480,00 1,664 2,240 3,000 1,800 9,600 7,55 286 286	1,293	3,878 1,187	4,344.00 2,184.00	18R 502
3,200 624 3,400 2,600 3,080 9,200 2,740 5,76 672	6,960,00 3,328 4,480 6,000 1,936 1,510 573	18,330 4,109 6,304	12,401 3,051 1,030	8,688 4,368	1,291 405
3,600 702 3,825 2,955 3,465 10,350 10,745 648 756	7,830,00 3,744 5,040 6,750 4,050 2,178 1,699 644 644	23,761 5,522 8,172	16,076 4,198	9,774 4,914	3BR 1,775 557
9,600 1,872 10,200 7,800 9,240 13,800 13,800 1,298 2,016	10,440,00 4,992 6,720 9,000 5,400 2,904 2,286 659 859	37,766 8,918 12,989	25,651 7,120 2,402	13,032 6,552	4BR 3,012 3,012
2,400 468 2,550 1,950 2,310 3,450 915 324	2,610,00 1,248 1,680 2,250 1,350 1,350 566 215 215	9,442	6,388 2,034 6,888	3,258 1,638	5,400 5,400 861 861 270
20,400 3,978 26,575 16,575 19,635 41,400 10,980 3,132 4,284	31,320,00 14,976 20,180 27,000 16,200 8,712 6,797 2,578 2,578 130,320	5,729 18,330 23,761 37,768 37,768 41,08 4,108 4,108 5,822 6,938 6,938 1,939 1,	3,978 12,401 19,0076 25,551 6,393 1,189 7,129 3,051 4,129 7,129 1,000 1,416 686 87,816	39,096 19,656 58,752	5,000 5,000 1,291 1,291 1,291 1,291 1,291 1,291 1,291 1,291 1,291 1,405 4,05 4,05 4,05 4,05 4,05 4,05 5,07 5,07 5,07 5,07 5,07 5,07 5,07 5
	19 ,320	149,994	87,816	58,752	grand total
Same bathroom deeign used for all units. Note that 4BR and 5BR units have 1.5 baths. For these, the work associated with the lub is only counted once but other items counted twice.	Same kitchen design used for ell units.	Paint all interior spaces.	New baseboard and trim package proposed 3-1/2" stock pine base 16.3 UF/Door © \$5.201 = \$84.76	Existing stairs are very narrow (+/-3) and steep (8" risers). Upgrade of linishes will improve perceptions of this item.	Comments 4.0 windows/unit 1.75 windows/unit 2.25 windows/unit 2.5 windows/unit 3.5 windows/unit 4.0 windows/unit 1.75 windows/unit 2.75 windows/unit 3.5 windows/unit

	moens means	means means means means means means	meens	meens	meens meens meens meens meens oomp meens oomp meens meens meens meens meens meens meens meens	meens
	Electrical Provide New house meter Provide new house panel New circults, switches and outlets - 1BH st New circults, switches and outlets - 2BH st New circults, switches and outlets - 2BH st New circults, switches and outlets - 3BH st New circults, switches and outlets - 3BH st New circults, switches and outlets - 3BH st Hardwirds annote detectors - 1BH st Hardwirds annote detectors - 1BH EA Hardwirds annote detectors - 3BH EA	Plumbing Repair/Replace deteriorated plumbing lines F	Mechanical New HVAC gyatem - 1BR el New HVAC gyatem - 2BR el New HVAC gyatem - 3BR el New HVAC gyatem - 3BR el New HVAC gyatem - 4BR el New HVAC gyatem - 5BR el Add dyne ordnust ductivent - 1 BR el Add dyne ordnust førs el existing baltis - 1BR el Add dehaust førs el existing baltis - 2BR el Add dehaust førs el existing baltis - 2BR el Add dehaust førs el existing baltis - 2BR el Add dehaust førs el existing baltis - 5BR el Add dehaust førs el existing baltis - 5BR el New yas møders el	Visitabiliy Modifications Widen entratos to receive eccessible door EA	Added Thermal insulation in attics and walls R-30 blown insulation at attics - IBR R-30 blown insulation at attics - 3BR R-30 blown insulation at	Item Coaramic wall tile (tub surround and walnscol) state
	275.00 36 9,900	5.00 5.0 2.50 19.50 19.50 2.50 19.50 1	367 367 367 367 367 367 367 367	625.00 1 625.00	112 308 344.96 112 483 551.60 112 568 635.60 112 567 757.68 100.00 1 100.00 10.96 182 789.34 1.572.66 1.586 1,586 1,457.26 1.696 1,586 1,736.66 1.696 1,586 1,736.66	Marie Coef QY Coef
Page 4 of 5	7,382 23,640 30,645 600 2,000 2,700 2,700 6,440 12,890 14,490	1,000 2,000 2,250 1,572 3,144 3,537 5,000 10,000 11,250 4,000 8,000 9,000 1,000 2,000 8,775 1,000 2,000 2,250	1,200 2,400 2,700 500 1,000 1,125 500 1,000 1,125	1,875 4,375 5,000	1,990 4,413 5,720 400 800 900 3,193 10,138 13,116	188 288 389 1,037 1,339 8,257 1,917 3,833 4,312 288 590 1,053 422 844 277 446 277 540 568 270 560 568
	49,708 12,177 4,200 1,200 19,200 4,800	3,000 750 4,716 1,179 15,000 3,000 11,700 2,925 3,000 750	3,600 900 1,500 375	6,875 1,250	9,092 2,273 1,200 300 20,833 5,208	4BR 5BR 19.513 4,128 8.625 2,156 2.15 2.15 2.15 2.15 2.15 2.15 2.15 2.15
	9,900 64,900 7,392 20,3440 12,177 18,000 2,700 1,200 1	9,000 14,148 45,000 35,100 9,000 148,248	10,800 4,500 4,500 1,105 1,105 1,105 21,675 21,675	19,375 19,375	1.380 4.4(3) 5/720 2.273 3.600 3.1600	33,907 20,943 2,574 1,046 5,567 1,046 5,508 5,508 5,508 2,754 3,443 3,443 224,100 224,100
	Addition of HYAC equipment, Washers, Dryers and Dishwashers requires new savice and distribution at each unit. Context in kit, Irving, BFIs, Hell.	All damagod piping to be replaced, and new piping to be provided as required for new kitchen and belth configurations. served leafus observed in units, perificularly at kitchens below 2nd floor behindoms. Cathrooms. Remote-need submeter.	Ensiting units include floor heaters, passifind with not ductwork distribution. A new forced air system with exterior condensers is proposed. TBD	Accessible anianos provided at each unit. This applies to 616 units.	Buildings tack insulation in entire envelope. Slown insulation is proposed for aftic spaces. Rigid insulation is proposed to be added to the inside of exterior wells (behind GWB). Repairs to support add'i lossling and replace deteriorated supports.	Comments

Renovati		General Bid Based Bid Based Bid Based Bid Based Bid Based Bid Based Bid Based		Asbectos Bid Based	source Item
Renovate Existing Common Buildings UFAS modifications - Common Buildings	AHA Administration 3%	General Conditions Affe Fees (8%) Contingency (2.5%) Flatosation Insurance/Bond Construction Management Fee (2%)		Asbesios Abelemen Overall Project Asbesios Abelement	
r.		ত্র ভারতা		Ē	unit .
6000		248, 189.25 77,559.14 200,000.00 62,047.31		2,500.00	unit cost
_		<u> </u>		36. 00	qty
80,000		248,189.25 77,559.14 185,000 200,000.00 62,047.31		90,000.00	00
					1BR
					2BR
					388
					4BR
					SBR
60,000	TOTAL New Total 2009 TDC % of TDC	248,189 77,559 185,000 200,000 62,047 772,796	SUBTOTAL	90,000.00	subtotal
	3,875,161 116,255 3,981,416 8,929,620 44,70%	772,796	3,102,366	90,000	grand total
Allowance for UFAS renovations at Learning Center				Asbestos abalament for all residential and non-residential buildings. Cost based on 2008 actual demolition cost for 148 units.	comments

Conversion textors based on 2Br unit SF 2BR SF 1BR 2BR 3BR 4BR 5BR

985 616 985 1135 1353

63% 100% 115% 137% 137%